Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329
Inspection Date(s): 7/10/2014, 7/7/2014 (Half), 7/8/2014, 7/9/2014	Man Days: 3.5
Inspection Unit: Central Shop	
Location of Audit: Chicago	
Exit Meeting Contact:	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Steve Canestrini	
Company Representative to Receive Report: Tom Webb	
Company Representative's Email Address: TJWebb@peoplesgasdelivery.com	

CONSTRUCTION INFORMATION				
Location of Construction:	Construction Performed By:			
5400 block of West Quincy	Intren Constructi	on		
Contractor Foreman:	·			
Operator Inspector:				
Person(s) On Job Site				
Frank Robeldo	Dave Fitzgerald	Brad Lasko		
Charles Keaton	Nate Rodriguez	Victor Minicks		
Tyree Washington	Scott Seifred			
Description of Construction:				

SERVICE INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.619,192.621,192.623]	MAOP	25 PSIG
[192.5]	Class location :	4
[192.53]	Are components qualified for use?	Satisfactory
General Comment:	•	•

Intren Construction was installing a 1" PE service at 5401 W Quincy thru directional boring.

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Pipe Size :	1"
Specification :	PE 2406/2708
Manufacturer:	DriscoPlex
Pipe Grade :	D2513
Wall Thickness :	0.315
Are pipe, valves, and fittings properly marked for identification?	Satisfactory
dentification	
Welder qualification date:	Not Applicable
Welder's Name:	Not Applicable
Is pipe joined in accordance with approved written procedures?	Satisfactory
e. Staff requested that Peoples Gas remove the fusion. Staff then questioned th blain the proper procedures to follow. Staff observed a fusion that he previously numbers which was found to be acceptable. Based on the fusion operator's knowledge, all consider the section satisfactory.	nade, along with
Date of Qualification :	5/14/2014
Joiner's name:	Dave Fitzgerald
Is buried metallic pipe coated?	Not Applicable
Is cathodic protection being provided?	Not Applicable
Is cathodic protection being provided? By Anodes:	No
Is cathodic protection being provided? By Rectifier:	No
Does coating meet 192.461?	Not Applicable
	Specification: Manufacturer: Pipe Grade: Wall Thickness: Are pipe, valves, and fittings properly marked for identification? Mentification Welder qualification date: Welder's Name: Is pipe joined in accordance with approved written procedures? Procedures? Staff requested that Peoples Gas remove the fusion. Staff then questioned the lain the proper procedures to follow. Staff observed a fusion that he previously in which was found to be acceptable. Based on the fusion operator's knowledge, all consider the section satisfactory. Date of Qualification: Joiner's name: Is buried metallic pipe coated? Is cathodic protection being provided? By Anodes: Is cathodic protection being provided? By Rectifier:

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
PE installation		
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:		
PE installation		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Satisfactory
General Comment:		
The service riser was cleaned and jacketed.		
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
PE service installation.		
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
General Comment:		
The ditch was properly back-filled to provide support for	the main and service.	
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
General Comment:		
The service was installed to minimize any shear or tensi-	lle forces being applied.	
[192.321]	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:		
A tracer wire was installed next to the PE service. The t	racer wire was then connected to the locate wire for the main.	
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
General Comment:		
Did not observe any underground structures near the ins	stallation.	
Is required cover being obtained for the servi	ce line?	Satisfactory
General Comment:		
The service was approximately 32" in depth. The main to	was approximately 39" in depth.	
[192.503]	Are general testing requirements being met?	Not Checked
General Comment:		
Did not observe any testing of facilities.		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.517]	Are records being made of strength and leak tests?	Not Checked
General Comment:		
Did not observe any testing of facilities.		
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
General Comment:	·	
Reviewed the qualification records for the e	mployees on the job site. All were qualified in the tasks being performed.	
[192.805(c)]	Were non-qualified personnel being "directed and observed" by a qualified individual?	Not Applicable
General Comment:	·	
All employees on the job site were qualified	in the tasks assigned.	
[192.805(c)]	Were span of control limitations being followed?	Not Applicable
General Comment:	·	
All employees on the job site were qualified	in the tasks assigned	
Was a Protocol 9 (Form 15) Compl	leted?	No
[192.614]	Were One Call Notifications performed as required?	Satisfactory
General Comment:	·	
Reviewed the dig and permit for the location	n. Both were valid for the dates and location of the excavation.	
[192.614]	Dig Ticket #	467419367
[192.383(b)]	Is an EFV installed on any new or replaced service line serving a single-family residence?	Satisfactory
General Comment:		
An EFV was installed as a component of the	e service tee.	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.